

30 REQUIRED FOR OPTIONAL VAV.

FAILURE TO DO SO MAY CAUSE
DAMAGE TO THE EQUIPMENT.

STANDARD INDOOR FAN MOTOR