



# Installation

# PART-IN-35

Library	<b>Service Literature</b>
Product Section	<b>Service Products</b>
Product	<b>Parts</b>
Model	<b>SPHA</b>
Literature Type	<b>Installation</b>
Sequence	<b>35</b>
Date	<b>April 1999</b>
File No.	<b>SV-SP-000-PART-IN-35-499</b>
Supersedes	<b>New</b>

## Replacement of RLY00742

Internal changes have been made to relay board RLY00742. Connector A1J1 was changed from a 9 pin connector to a 6 pin connector. Only 5 of these pins are used on both the original and the replacement board. When using a newer version of RLY00742 with 6 pins at connection A1J1 to replace an older version that has 9 pins at A1J1, it is necessary to use different pin numbers when reconnecting the molex plug to A1J1. Follow Table 1 below:

**Table 1 — Pin Numbers**

Equivalent pin designations for replacement 6 pin version of A1J1	1	4	3	5	6
Pin designations for 9 pin version of A1J1	1	4	7	5	8

Since The Trane Company has a policy of continuous product improvement, it reserves the right to change specifications and design without notice.