

NOTES:

1. COAT MACHINED SURFACES WITH COMPRESSOR OIL.
2. WRAP ASSEMBLY IN PLASTIC BEFORE PLACING IN BOX FOR SHIPPING. (TO PREVENT DIRT FROM GETTING INTO ASSEMBLY)
3. ITEM 121 and 114 SHOULD SHIP LOOSE.

